Notebook, PN-91-00-00.2

This undated pocket notebook was used by Edison around 1891 for notes relating to filament experiments. There is also a set of calculations, possibly pertaining to ore milling, and two rough drawings. The pages are unnumbered. Only 9 pages have been used.



Investigate the film on lamps. See if that is a film formed before. Lamp has burned sufficient to tint it - also test chemically & spectroscopically nature of film - Try lamp that has been worked off req on pumps for film - get thickness of film by Microscope for scarcely tinted + very black lamps see if diffusion = pass CS_2 + H through tube to deposit - also, air

Its very likely that the Molecules of gas are held Even against Vacuum by the static attraction of the glass globe which is very powerful. This Expmnt to ascertain if more gas can be thrown in & all into by Changing the Globe Electrically & reversing the charge with grt rapidity during exhaustion.

Try Expmnt of Thermits can pump it Chamber with platina loop around it to heat it taking time of Cooling to measure deg of Vacuum

Take up Storage battery Expert
- use Carbyd Chemicals powdered
Zinc + $ZnSO_3$ + Sulphuric
acid. Try P+N Battery up
Anthracite deposit from
head —

Believe can for same weight as
Wire in Sims Torpedo put
storage battery to run home
3 miles - using simple fine
wire to steer - get Copy.
Sims patent, to get claims

Clean globe & put some Linseed oil thin film inside Lamp.

Lamp in tube with phos and get nearly and - Expell air + absorb moisture then not inside tube in lamp heat lamps 24 hrs with Lampblack in Cove flame + Gueb hat,

get absorbent for Nitrogen =

Write Keller works 50 East 42nd

polish + get curve

Use lampblack previously heated to drive off hydrocarbons immerse in gasoline squeeze + put in dried Lamp -